



MarS a.s., Okružní II. čp. 239, 569 43 Jevíčko

CZECH REPUBLIC

**SERVICE  
BULLETIN**

## **SERVICE BULLETIN no. 2/08/2008**

### **The Suspension of Parachute Jumping**

- 1. APPLIES TO:** the systems containing the following parts:
- **the WP –175 reserve parachute**
  - **the OP-087 container, size 4N**
  - **the MPAAD safety device.**

(This service bulletin does not apply to such systems in which the container, size 4N, is equipped with the WP-210 reserve parachute or PZS-92 parachute or the safety system is other than an MPAAD device).

- 2. REASON:** Due to an extraordinary event which occurred at the airport in Prostějov on August 7, 2008, i.e. a case of a proper functioning of the safety device but improper functioning of the system containing the above specified container and reserve parachute.

- 3. MEASURES:** Until cancelled, suspend parachute jumps to take place using the systems with the following configuration:
- the WP-175 reserve parachute
  - the OP-087 container, size 4N
  - the MPAAD safety device.

- 4. VALIDITY:** Upon the date of this Bulletin´s issue.

- 5. DATE OF ISSUE:** In Jevíčko, on August 13, 2008

Jaroslav Sedlák - Head of Technical Department  
MarS a.s. Jevíčko

Stamp, signature:

